CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 3438

Title: North American Yale serial:3438 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-June-12. Yale s/n 3438. This accident involved 2 people. Clarfield L, Harndon SK

Keywords: RCAFYale ,3438,3 WS,3 Wireless School,Steinback Manitoba,1944-June-12,Clarfield,HarndonRCAF L20

Created: 1944-06-12

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001795#3438

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
# 3 W.S.	2	Steinback,Man.	12-6-44	0900

H.Q. FILE 1100-34-38

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
YALE	3438	~~NIL~~ E	X		X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Harndon, S.K.	P/O		P	Nil
Clarfield,L.	LAC	R186034	WO	Nil

SIGNAL: NO. No sig. DATE

D 14 (REVISED): NO. 1 CHECKED

1

ENGINE	ENGINE NUMBER (S)
Wright Whirlwind.	15056/18676 Ser.

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
41	12	33	1	402	137

TYPE OF A/C | TYPE OF UNIT | CATEGORY | COMMAND | MONTH | STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY | INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Wireless exercises.

NATURE OF ACCIDENT:

Pilot had been out on wireless exercises about twenty minutes. Oil temp. ran above normal, and engine suddenly lost all power and forced landing was made in a field.

TECHNICAL OFFICER'S REPORT:

Engine failure.

FE/1001/2 5/1/41/1/42

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble-accident.

ACTION TAKEN:

Nil.

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 665-L 20

C. C. LTD. 7084-43