CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6111

Title: Avro Anson Mk. I serial:6111 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-02. Anson I s/n 6111. This accident involved 3 people. Grainger R, Taylor GB, Trumphour FW

Keywords: RCAFAnson I,6111,7 AOS,7 Air Observer School,Souris Airport,1944-August-02,Grainger,Taylor,TrumphourRCAF L20

Created: 1944-08-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6111

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S., Portage la Prairie	2	Souris Airport	2-8-44	1140

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6111	"E"		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Taylor, C.B.	SGT	R163134	P	Uninj.
Trumphour, F.W.	LAC	R255212	WAW	Uninj.
Crairger, P.	LAC	CR1625962	WAW	Uninj.

SIGNAL

NO. | DATE

D 14 (REVISED)

NO. | CHECKED

#7

ENGINE	ENGINE NUMBER (S)
Cheetah IX	A133587/AS16421 Nil
	138987/AS23165 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
65	116	143	450	184	485

TYPE OF A/C | TYPE OF UNIT | CATEGORY

COMMAND | MONTH | STAGE OF FLIGHT

FORCED LANDING | TAXYING | LANDING | TAKE-OFF | FLIGHT | STAT'RY

INJURY: FATAL | INJ. | 3RD | S | NIL

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation Exercise.

NATURE OF ACCIDENT:

Stbd. inner fuel cock failed to operate necessitating landing at nearest airport, Souris, P.E.A.F.

TECHNICAL OFFICER'S REPORT:

Thread stripped on fork end sliding rod stbd. gas cock.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: **SUMMARY No.**

SFE/ET/PF/D/E

CLASSIFICATION:

18. Misc. Technical.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Nil.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 685-L 20

C. C. LTD. 20157-44