CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11333

Title: Avro Anson Mk. II serial:11333 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-03. Anson II s/n 11333. This accident involved 1 person. Mahoney BW

Keywords: RCAFAnson II,11333,17 SFTS,17 Service Flying Training School,Gaynemer Manitoba,1944-August-03,MahoneyRCAF L20

Created: 1944-08-03

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11333

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S. Souris, Man.	2	Vicinity of Gaynemer, Man.	3-8-44	1030

H.Q. FILE 1100-113-33

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11333	"D"2		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Mahoney, B.W.	LAC	R196880	PP	Slightly

SIGNAL

NO.	DATE
A176	3-8

D 14 (REVISED)

NO.	CHECKED

#7

ENGINE	ENGINE NUMBER (S)
L6MB	P25008/P9378 S16488/S2667

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
54	22	104	51	140	83

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

No. 8 Cross Country.

NATURE OF ACCIDENT:

Pilot reports that he fainted in air at normal cross country height. hit ground recovered and flew a/c back into Paulson aerodrome.

TECHNICAL OFFICER'S REPORT:

Nil.

ILCG/PM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CAUSE: Cause of a/c striking ground was loss of control occasioned by the pupil pilot losing consciousness due to carbon monoxide poisioning.

RECOMMENDATIONS: Nil

CONCLUSIONS OF A.I.B.: Agree with findings.

CLASSIFICATION:

20. Flew into Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44