CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 12140

Title: Avro Anson Mk. V serial:12140 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-03. Anson V s/n 12140. This accident involved 5 people. Doe, Dunning, Gudmunsen , Johnson AC, Sims

Keywords: RCAFAnson V,12140,8 AOS,8 Air Observer School,Aerodrome,1944-August-03,Doe,Dunning,Gudmunsen,Johnson,SimsRCAF L20

Created: 1944-08-03

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#12140

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
8 A.O.S. Ancienne Lorette	3	M.A.	3-8-44	0050

H.Q. FILE 1100-121-40

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	12140	"E"		X		X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
JOHNSON, A.C.	SGT	R188540	P	Uninj.
SIMS, GB	CPL	1293016	NAV	Uninj.
DOE, GB	LAC	1802150	NAV	Uninj.
DUNNING,	LAC	1145648	NAV	Uninj.
CUDMUNSEN, GB	LAC	1605525	WOAC	Uninj.

SIGNAL

NO. No sig DATE

D 14 (REVISED)

NO. CHECKED

#3

ENGINE	ENGINE NUMBER (S)
Wasp Jr.	19435/14365 Nil
	20741/43-4555

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
51	68	121	268	162	300

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine navigation exercise.

NATURE OF ACCIDENT:

Undercarriage folded on landing;

TECHNICAL OFFICER'S REPORT:

Electrical system failed in flight. Could not Instruct WOG to change batteries in air so that he would have enough power for Nav. lights and warning devices.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

LUA/UDM

CLASSIFICATION:

18. Misc. Technical.

SECONDARY OR CONTRIBUTORY FACTORS:

35. U/C defect.

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44