CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6021

Title: Avro Anson Mk. I serial:6021 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-05. Anson I s/n 6021. This accident involved 4 people. Kerr GE, Lavitt AL, Swan JE, White A

Keywords: RCAFAnson I,6021,7 AOS,7 Air Observer School,Rivers Rcaf,1944-August-05,Kerr,Lavitt,Swan,WhiteRCAF L20

Created: 1944-08-05

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6021

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S. Portage la Prairie	2	Rivers, R.C.A.F.	5-8-44	0030

H.Q. FILE 1100-60-21

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6021	"E"		X		X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
SWAN, J.E.	SGT	R150900	P	Uninj.
KERR, G.E.	LAC	R277813	NAV	Uninj.
LAVITT, A.L.	LAC	R166079	NAV	Uninj.
WHITE, A.	CPL	R204677	WOP	Uninj.

SIGNAL

NO.	DATE
No sig	

D 14 (REVISED)

NO.	CHECKED
4	

#10

ENGINE	ENGINE NUMBER (S)
Cheetah IX	A272353/AS35462 Nil
	13314, AS16699 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
60	354	114	989	150	1030

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

Forced Landing
Taxying
Landing
Take-off
Flight
Stat'ry
Fatal
Inj.
3rd
S
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Stbd engine became rough necessitating landing at nearest airport,

TECHNICAL OFFICER'S REPORT:

No. 5 exhaust valve burned stbd engine.

SFE/ET/VA/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: **SUMMARY No.**

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage.

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44