CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6293

Title: Avro Anson Mk. I serial:6293 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-06. Anson I s/n 6293. This accident involved 4 people. Brown HW, Forrest JF, Miller CB, Seaman WA

Keywords: RCAFAnson I,6293,7 AOS,7 Air Observer School,Aerodrome,1944-August-06,Brown,Forrest,Miller,SeamanRCAF L20

Created: 1944-08-06

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6293

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S. Portage la Prairie	2	M.A.	6-8-44	1645

H.Q. FILE 1100-62-93

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6293			X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
BROWN, H.W.	P/O	J46648	P	Uninj.
FORREST, J.F.	LAC	R287855	NAV	Uninj.
SEAMAN, W.A.	LAC	R276647	NAV	Uninj.
MILLER, C.B.	LAC	R278727	NAV	Uninj.

SIGNAL

NO.	DATE
No sig	

D 14 (REVISED)

NO.	CHECKED
7	✓

#14

ENGINE	ENGINE NUMBER (S)
Cheetah IX	10330/AS03584 Mil
	10225/AS30676 Mil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
55	476	93	1292	127	1324

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
S
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Port engine very rough necessitating return to base.

TECHNICAL OFFICER'S REPORT:

No. 5 cylinder exhaust standard bushing broke port engine.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: **SUMMARY No.**

SFE/ET/MP/D/I

CLASSIFICATION:

17. Forced landing.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage.

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 685-L 20

C. C. LTD. 20157-44