CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 716

Title: Hudson III serial:716 - Crash Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-August-26. Hudson III s/n 716. This accident involved 2 people. Cook GM, Doyle MG

Keywords: RCAFHudson III,716,11 Sqn,11 Squadron,Aerodrome,1944-August-26,Cook,DoyleRCAF L20

Created: 1944-08-26

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
11 (BR) Dartmouth, N.S.	EAC	M.A.	26-8-44	1850Z
			H.Q. FILE	1100-7-16

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
HUDSON III	716	"A"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Doyle, M.G.	G/C	C195	PP	Uninj.
Cook, G.M.	W/C	C1059	Capt.	Uninj.

SIGNAL — NO. — DATE

D 14 (REVISED) — NO. — CHECKED

#3

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
Wright Cyclone	60145/39505 Unknown			3		90	14
		112	523	6	450	70	2300

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STAT'RY · INJURY · FATAL · INJ. · 3RD · S · RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:
Check out of G/C Doyle on type.

TECHNICAL OFFICER'S REPORT:
Nil.

OS/PSS/USS

NATURE OF ACCIDENT:
A/C swung as pupil pilot opened throttles. Apparently tailwheel had not locked PP attempted correction by throttles, then hauled them off and applied brakes as a/c ground-looped out of control about 200 yds from start of take-off run.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:
FINDINGS:
SUMMARY No.

CLASSIFICATION:
12. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:
Nil.

R. C. A. F. L 20 (REVISED)
2M-9-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44