CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6984

Title: Avro Anson Mk. I serial:6984 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-September-06. Anson I s/n 6984. This accident involved 5 people. Evans TA, Fletcher RG, Goldthrop S, Small P, Wrightson KC

Keywords: RCAFAnson I,6984,7 AOS,7 Air Observer School,Aerodrome,1944-September-06,Evans,Fletcher,Goldthrop,Small,WrightsonRCAF L20

Created: 1944-09-06

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6984

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S. Portage la Prairie	2	M.A.	6-9-44	0010

H.Q. FILE 1100-69-84

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6984	"E"		X		X

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
EVANS, T.A.	SGT	R80123	P	Uninj.
WRIGHTSON, K.C. GBLAC		1698522	NAV	Uninj.
FLETCHER, R.G. AUS	LAC	443303	NAV	Uninj.
GOLDTHROP, S.	SGT	R117835	NAV	Uninj.
SMALL, P.	CPL	R204510	WOG	Uninj.

SIGNAL: NO. No sig; DATE

D 14 (REVISED): NO. 3; CHECKED ✓

#5

ENGINE	ENGINE NUMBER (S)
Cheetah IX	10664/AS31681 Nil A10974/AS31515 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
58	176	136	441	173	480

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STAT'RY · FATAL · INJ. · 3RD · INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Port engine failed necessitating return to base.

TECHNICAL OFFICER'S REPORT:

Exhaust valve guide number 2 cylinder port engine burned.

SFE/ET/VA/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: **SUMMARY No.**

CLASSIFICATION:

18. Misc. technical.

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage.

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K.P. 8669
H. Q. 885-L 20

C. C. LTD. 20157-44