CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: AX415

Title: Avro Anson Mk. I serial:AX415 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-September-08. Anson I s/n AX415. This accident involved 2 people. McCutcheon HD, Quinn FC

Keywords: RCAFAnson I,AX415,4 BGS,4 Bomb & Gunnery School,Aerodrome,1944-September-08,McCutcheon,QuinnRCAF L20

Created: 1944-09-08

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#AX415

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
4 B.G.S. Fingal	1	M.A.	8-9-44	1405

H.Q. FILE 1300-AX415

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	AX415	"D"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
QUINN, F.C.	F/O	J28630	P	Uninj.
MCCUTCHEON, H.D.	P/O	J44464	2P	Uninj.

SIGNAL

NO.	DATE
No sig	

D 14 (REVISED)

NO.	CHECKED
1	✓

#4

ENGINE	ENGINE NUMBER (S)
Cheetah	10184/AS30609 Nil 10920/AS31633 serious

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
70	159	10	433	163	544
50	16	77	158	180	256

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

RAF
M

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Instrument practice.

NATURE OF ACCIDENT:

Stbd engine seized at 50' above ground on take off and engine caught fire. Made wheels down, landing on own aerodrome.

TECHNICAL OFFICER'S REPORT:

Investigation of engine showed considerable oil in induction system, possible from leakage past a worn supercharger bearing.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

OFM/ADP/ESDM/DD/AE

CLASSIFICATION:

15. Forced land.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine trouble - accident

28. Fire - in air

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4636) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44