CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11912

Title: Avro Anson Mk. V serial:11912 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-September-23. Anson V s/n 11912. This accident involved 1 person. Mcmurray TB

Keywords: RCAFAnson V,11912,1 AOS,1 Air Observer School,Aerodrome,1944-September-23,McmurrayRCAF L20

Created: 1944-09-23

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11912

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 A.O.S. Malton	1	M.A.	23-9-44	1745

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	11912	"C"		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
McMurray, T.B.	AC2	R297003	P	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
	✓

#8

ENGINE	ENGINE NUMBER (S)
Wasp Jr P&W	S. 14412/210812
R985AN14-B	P. 14499/210899 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
22	483	2	215	40	1392

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATRY

INJURY
FATAL
INJ.
3RD
S
N

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

First Solo on this Type

NATURE OF ACCIDENT:

A/C seriously damaged due to ground loop.

Runway in use was very much out of wind.

TECHNICAL OFFICER'S REPORT:

Nil. LS/PSS/USS/KCA/WWC

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

None as yet.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 6689
H. Q. 665-L 20

C. C. LTD. 20157-44