CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 3438

Title: North American Yale serial:3438 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-September-21. Yale II s/n 3438. This accident involved 2 people. Draught HR, Guest J

Keywords: RCAFYale II,3438,3 WS,3 Wireless School,Rivers Manitoba,1944-September-21,Draught,GuestRCAF L20

Created: 1944-09-21

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001795#3438

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
3 W.S. Calgary	2	Rivers, Man	21-9-44	1050

H.Q. FILE: 1100-34-38

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
YALE II	3438	E	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
GUEST, J.	P/O	J44926	P	Uninj.
DRAUGHT, H.R.	LAC	R87961	WO	Uninj.

SIGNAL: NO. No sig; DATE

D 14 (REVISED): NO. 3; CHECKED ✓

#5

ENGINE	ENGINE NUMBER (S)
Wright Whirlwind R975E3	15126/18599 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
26	8	2	54	89	119

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY · INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Wireless exercise.

NATURE OF ACCIDENT:

Pilot had taken off and reached his target. After turning to return to base he noticed black smoke issuing from engine cowling and coming into the cockpit. He still was 1½ hours of flying time from base, so he decided to land while he still had power available at Rivers, Man. Engine was running very rough and the cylinder head heat was rising.

CLASSIFICATION:

17. Forced landing.
18

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine trouble - no damage.

TECHNICAL OFFICER'S REPORT:

No. 1 and No. 3 pistons ring seizure.

SFE/ET/11M/D/I

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

NIL

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44