CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6658

Title: Avro Anson Mk. I serial:6658 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-October-11. Anson I s/n 6658. This accident involved 5 people. Grant DC, Little RE, Martin DA, Whitley MH, Wilson RAH

Keywords: RCAFAnson I,6658,7 AOS,7 Air Observer School,Airport,1944-October-11,Grant,Little,Martin,Whitley,WilsonRCAF L20

Created: 1944-10-11

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6658

ACCIDENT CLASSIFICATION

UNIT	COM	PLACE	DATE	TIME
7 A.O.S.	2	Airport No. 7 A.O.S.	11-10-44	16.20

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6658	"E"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
MARTIN, D.A.	F/Sgt.	R164187	P.	Uninj.
WHITLEY, M.H.	LAC	R268429	1 Nav.	Uninj.
WILSON, R.A.H.	LAC	GB1608059	2 Nav.	Uninj.
~~LITTLE, R.E.~~	LAC	GB1473529	A.B.	Uninj.
~~GRANT, D.C.~~	Cpl.	~~R192757~~	WOG	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
	✓

13

ENGINE	ENGINE NUMBER (S)
CHEETAH IX	P10923/AS31614 Nil
CHEETAH	10135/AS30497 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
71	333	45	805	190	900

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY
FATAL
INJ.
3RD
S

RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise.

NATURE OF ACCIDENT:

Port engine failed just before completion of exercise necessitating single engine landing at base.

TECHNICAL OFFICER'S REPORT:

Thread stripped on valve standard # 4 cylinder Port motor.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

SFE/ET/VA/D/E

CLASSIFICATION:

18. Misc. Technical

SECONDARY OR CONTRIBUTORY FACTORS:

27. Engine Trouble - No damage.

ACTION TAKEN:

nil

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44