CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11352

Title: Avro Anson Mk. II serial:11352 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1944-December-04. They are: Anson V s/n 12277, Anson II s/n 11352. This accident involved 2 people. Lindsay J, Stuart DA

Keywords: RCAFAnson II,11352,17 SFTS,17 Service Flying Training School,Rivers Manitoba Airport,1944-December-04,Lindsay,StuartRCAF L20

Created: 1944-12-04

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11352

ACCIDENT CLASSIFICATION

UNIT #1 CNS Rivers Man. COM. 2
#17 SFTS Souris Man.

A/C TYPE ANSON V
ANSON II

PLACE No. 1 C.N.S.
Rivers, Man., Airport

NO. 12277
11352 -D

CRASH CAT. "D"
-

DATE 4-12-44 TIME 1153

H.Q. FILE 1100-113-52

S.E.	M.E.	DAY	NIGHT
	x	x	

COMMAND

MONTH 5-12

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY, INJURY (FATAL, INJ., 3RD, S)

TYPE OF A/C

TYPE OF UNIT

CATEGORY

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
STUART, D. A.,	F/O	J38123	P	Uninj.
LINDSAY, J., GB	LAC	1571334	PP	Uninj.

SIGNAL

NO. | DATE 5-12

D 14 (REVISED)

NO. 1 | CHECKED

9

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
Wasp Jr.	28249/210349 Undamaged						
~~Jacobs L6MB~~	~~28261/210361~~ "						
	~~25170/9540~~ "	94	76	111	317	232	801
	~~19745/25857~~ "	10	4	12	7	68	38

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Seq. 18-17-21-22-33-S.E.L.

NATURE OF ACCIDENT:

11352 from Souris landed and discovered brake trouble. Attempted to taxi into parking line. Brake apparently failed completely and propellor of 11352 chewed up port wing of 12277 which was parked on the line, unoccupied.

TECHNICAL OFFICER'S REPORT: MULT

Brake failure.

TCA/PCT/UBF MA/XA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

9. Collisions

SECONDARY OR CONTRIBUTORY FACTORS:

36. Brake failure

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 6689
H. Q. 885-L 20

C. C. LTD. 20157-44