CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11348

Title: Avro Anson Mk. II serial:11348 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1944-December-20. Anson II s/n 11348. This accident involved 2 people. Sigurdson BS, Thissen H

Keywords: RCAFAnson II,11348,17 SFTS,17 Service Flying Training School,Aerodrome,1944-December-20,Sigurdson,ThissenRCAF L20

Created: 1944-12-20

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11348

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S.	2	M.A.,	20-12-44	2150

H.Q. FILE 1100-113-48

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11348	"D"		x		x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
SIGURDSON, B. S.,	F/O	J21270	F.I.	Uninj.
THISSEN H., RAF	F/O	149163	P.P.	Uninj.

SIGNAL

NO.	DATE
LG A290	21-12

D 14 (REVISED)

NO.	CHECKED
8	

24

ENGINE	ENGINE NUMBER (S)
Jacobs	P14115/25426 Nil
L6MB	S25980/10684 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
~~112~~	~~177.~~	~~128~~	~~1106~~	~~228~~	~~1305~~
~~16~~	~~4.~~	~~32~~	~~19~~	~~73~~	~~48~~

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
S
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Taxying U/S Aircraft back to Hangar.

NATURE OF ACCIDENT:

Instructor taxying A/C back to Hangar, left taxi strip and taxied across lawn at side of hangar. Struck frozen snow hummock with port propellor, shattering both tips.

TECHNICAL OFFICER'S REPORT:

Nil TCO/PCT/XGM

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

10. Bad Ground.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44