CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11320

Title: Avro Anson Mk. II serial:11320 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-January-13. Anson II s/n 11320. This accident involved 1 person. Lawrence BE

Keywords: RCAFAnson II,11320,17 SFTS,17 Service Flying Training School,Aerodrome,1945-January-13,LawrenceRCAF L20

Created: 1945-01-13

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11320

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S.	2	M.A. 17 S.F.T.S.	13-1-45	13.15

H.Q. FILE 1100-113-20

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11320 ~~11377~~	"E" Nil		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
LAWRENCE, B. E., GB	LAC	1805944	PP	Uninj.

SIGNAL

NO.	DATE
LG A3	13-1

D 14 (REVISED)

NO.	CHECKED
2	

11

ENGINE	ENGINE NUMBER (S)
Jacobs	~~P15671/1881~~ Nil
~~L6MB~~	~~S17089/3268~~ Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
10	12	34	21		

TYPE OF A/C | TYPE OF UNIT | CATEGORY | COMMAND | MONTH | STAGE OF FLIGHT | INJURY

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STAT'RY

INJURY: FATAL, INJ., 3RD, S, NIL, RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Taxiing into line after solo Cross-Country ex.

NATURE OF ACCIDENT:

Student Pilot attempting to taxi between a/c and hangar, struck Stbd. propellor boss of parked a/c with port wing tip.

TECHNICAL OFFICER'S REPORT: MVLA

Nil TCA/PCT MA/KA

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN: 48 hours detention.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44