CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 12398

Title: Avro Anson Mk. V serial:12398 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-January-31. Anson V s/n 12398. This accident involved 3 people. Merchant PJH, Patterson JTA, Wakeling WT

Keywords: RCAFAnson V,12398,1 CNS,1 Central Navigation School,Moosomin,1945-January-31,Merchant,Patterson,WakelingRCAF L20

Created: 1945-01-31

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#12398

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 C.N.S. Rivers, Man.	2	6½ ml. N. of Moosomin	31-1-45	1700

H.Q. FILE 1100-123-98

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	12398	"B"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
MERCHANT, P.J.H.,	F/O	J41757	P.	Uninj.
WAKELING, W.T., GB	LAC	1866188	OC	Uninj.
PATTERSON, J.T.A., GB	LAC	2007229	OC	Uninj.

SIGNAL: NO. No Sig. DATE

D 14 (REVISED) NO. 1 CHECKED

24

ENGINE	ENGINE NUMBER (S)	HOURS FLOWN BY PILOTS					
		INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
Wasp Jr.	P29516/211416 Slightly S29512/211412 Slightly	57	132	10	257	157	602

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STATYRY · INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Day Nav. Ex.,

NATURE OF ACCIDENT:

Engines failed one after the other at 5000' approx. 30 mins. after changing from outer to inner tanks. Pilot forced landed wheels up striking a tree with stbd. wing being toward latter part of landing run.

TECHNICAL OFFICER'S REPORT:

FB/AOP/ESNW/1/UOK/B

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

26. Engine Trouble - Accident.

ACTION TAKEN:

Investigation

R. C. A. F. L 20 (REVISED)
2M-9-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44