CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 12206

Title: Avro Anson Mk. V serial:12206 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-February-02. Anson V s/n 12206. This accident involved 4 people. Dunn MA, Hockin JH, Lampert G, Moffat KC

Keywords: RCAFAnson V,12206,9 AOS,9 Air Observer School,Nova Scotia Runway,1945-February-02,Dunn,Hockin,Lampert,MoffatRCAF L20

Created: 1945-02-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#12206

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
9 A.O.S. St. Johns, Que.	1.	NS Runway	2-2-45	2350
			H.Q. FILE	1100-122-06

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	12206	"D"		x		x

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
LAMPERT, G.,	F/S	R190847	P.	Uninj.
MOFFAT, K.C.,	LAC	R289125	1 Nav.	Uninj.
HOCKIN, J.H.,	F/O	C24355	2 Nav.	Uninj.
DUNN, M.A.,	Sgt.	R183256	WAG	Uninj.

SIGNAL

NO.	DATE
A.2	3-2

D 14 (REVISED)

NO.	CHECKED
1	
2	

ENGINE	ENGINE NUMBER (S)
P. & W.	14210/19278 Nil
Wasp.	28969/20837 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
45	110	100	740	140	775

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
FATAL
INJ.
3RD
INJURY

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Routine Night Nav. Ex.,

NATURE OF ACCIDENT:

A/C landed after routine night nav. ex. After touching down, A/C swung to the left and swing could not be corrected. A/C entered snow drift on side of runway with the resultant damage. - right u/c sheered off.

TECHNICAL OFFICER'S REPORT:

Nil LS/PSS/USC/XCH

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

2. Swung.

SECONDARY OR CONTRIBUTORY FACTORS:

34. U/C Strain.

ACTION TAKEN:

Log Book endorsed "Carelessness".

R.C.A.F. L.20 (REVISED)
2M-5-44 (4638) K.P. 8689
H.Q. 685-L.20

C. C. LTD. 20157-44