CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11348

Title: Avro Anson Mk. II serial:11348 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-February-10. Anson II s/n 11348. This accident involved 1 person. Davis GS

Keywords: RCAFAnson II,11348,17 SFTS,17 Service Flying Training School,Elgin,1945-February-10,DavisRCAF L20

Created: 1945-02-10

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11348

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
17 S.F.T.S. Souris, Man.,	2	5 mls. S. and 5 mls. E. of Elgin.	10-2-45 H.Q. FILE 1100-113-48	1245

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11348	"D"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
DAVIS, G. S., GB.	LAC	1584889	P.P.	Uninj.

SIGNAL: NO. IG. A.22 — DATE 12-2

D 14 (REVISED): NO. 2 — CHECKED

14

ENGINE	ENGINE NUMBER (S)
Jaguars L6MB	P14115/25426 Nil S25980/10684 Nil

HOURS FLOWN BY PILOTS	INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
	16	17	52	32	98	67

TYPE OF A/C | TYPE OF UNIT | CATEGORY | COMMAND | MONTH | STAGE OF FLIGHT

STAGE OF FLIGHT: FORCED LANDING, TAXYING, LANDING, TAKE-OFF, FLIGHT, STATRY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo Armament Ex.,

NATURE OF ACCIDENT:

Student Pilot took off on inner tanks and switched over to outer tanks which had only 10 gls. in each. Engines subsequently failed and student did not correct failure.

TECHNICAL OFFICER'S REPORT:

Nil FB/AOP/PCDE/ES/PS/PC/1

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

17. Forced Landing.

SECONDARY OR CONTRIBUTORY FACTORS:

25. Petrol Shortage.

ACTION TAKEN:

Pilot's log book endorsed "Carelessness".

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44