CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 12331

Title: Avro Anson Mk. V serial:12331 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-March-09. Anson V s/n 12331. This accident involved 1 person. Hamon RW

Keywords: RCAFAnson V,12331,1 CNS,1 Central Navigation School,Sect 2 Township 16,1945-March-09,HamonRCAF L20

Created: 1945-03-09

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#12331

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
No. 1 C.N.S. Rivers, Man.	2	Sect. 2, Township 16, Range 3 W.2 (2½ ml.S.W. Whitewood)	9-3-45	1800

R.C.A.F. FILE 1100-123-31

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON V	12331	"E"		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
HAMON, R.W.,	F/O	J27649	P.	Uninj.

SIGNAL: NO. No Sig. DATE

D 14 (REVISED) NO. 1 CHECKED

7

ENGINE	ENGINE NUMBER (S)
Wasp Jr.	P.29182/JP211082 Nil
Wasp Jr.	S.29186/JP211086 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
62	434	115	1300	160	1350

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STAT'RY · INJURY: FATAL, INJ., 3RD S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Day Nav. Ex.

NATURE OF ACCIDENT:

Pilot flying a/c out of field after precautionary landing, failed to clear telephone wires on windward side and sheared off port stabilizer but maintained control and landed at Broadview, Sask.

CLASSIFICATION:

13. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

Nil FTO/P5J

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44