CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 3717

Title: Consolidated Liberator GR Mk. VI serial:3717 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1945-March-02. Liberator VI s/n 3717. This accident involved 4 people. Creasor GR, Mclean EH, Richardson JE, Shaw DA

Keywords: RCAFLiberator VI,3717,11 Sqn,11 Squadron,Dartmouth Nova Scotia,1945-March-02,Creasor,Mclean,Richardson,ShawRCAF L20

Created: 1945-03-02

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000168#3717

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
11 (BR) Sqdn.	E.	RCAF Stn. Dartmouth, N.S.	2-3-45	1755Z

H.Q. FILE 1100-37-17

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
LIBERATOR VI	3717	"C"		x	x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
McLEAN, E.H., CAN.	F/L	J15179	P.	Uninj.
RICHARDSON, J.E.,	P/O	J44592	P.P.	Uninj.
SHAW, D.A.,	Sgt.	R209150	P.P.	Uninj.
CREASOR, G.R.	F/S	R70242	F.E.	Uninj.

SIGNAL

NO.	DATE
A.27	2-3

D 14 (REVISED)

NO.	CHECKED

1

ENGINE	ENGINE NUMBER (S)
P. & W.	1. 8705/446048 Nil
R1830-65A	2. 8706/446058 Nil
	3. 8707/445999 Nil
	4. 8708/445989 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		DUAL	SOLO	DUAL	SOLO
40.	38	42			

TYPE OF A/C · TYPE OF UNIT · CATEGORY · COMMAND · MONTH · STAGE OF FLIGHT · FORCED LANDING · TAXYING · LANDING · TAKE-OFF · FLIGHT · STATRY · INJURY · FATAL · INJ. · 3RD · S · RAF

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Training.

NATURE OF ACCIDENT:

Taxiing accident proceeding to parking place following instructions of linesman. Captain taxiing from right hand side. A/C turned to stbd. and struck telephone post.

TECHNICAL OFFICER'S REPORT:

Nil TCO/PCT/XCG

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: **SUMMARY No.**

CLASSIFICATION:

9. Collisions.

SECONDARY OR CONTRIBUTORY FACTORS:

ACTION TAKEN:

Pilot's log book to be endorsed.

R. C. A. F. L 20 (REVISED)
2M-5-44 (4638) K. P. 8689
H. Q. 885-L 20

C. C. LTD. 20157-44