CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: P3869

Title: Hawker Hurricane Mk. I serial:P3869 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 2 aircraft on 1940-August-27. They are: Hawker Hurricane s/n P3872, Hawker Hurricane s/n P3869. This accident involved 1 person. Little TB

Keywords: RCAFHawker Hurricane ,P3869,1 Sqn,1 (CAN) Squadron,North Weald Aerodrome,1940-August-27,LittleRCAF L20

Created: 1940-08-27

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000894#P3869

UNIT: No.1 (Can) Squadron, Northolt | PLACE: North Weald Aerodrome | DATE: 27-8-40 | TIME:

A/C TYPE: Hurricane Hurricane | NUMBER: P.3872 P.3869 D | CRASH: CATEGORY: Cat 2 | H.Q.FILE NO: 1021-4-1 F.D.305

OCCUPANTS

NAME	RANK	NO.	CLASS	EXTENT OF INJURIES	FLYING TIME: INST	NIGHT	ON TYPE DUAL	ON TYPE SOLO	TOTAL DUAL	TOTAL SOLO
Little, T.B.	F/O.	C1117	P	Uninjured						

Flying Accident

ACCIDENT CLASSIFICATION: SERIOUS | FATAL | INJURY

THIRD PARTIES:

PARACHUTE DESCENT:

AIRFRAME	DATE PURCHD	HOURS SINCE	LAST CPTE O'HAUL DATE	LAST CPTE O'HAUL HRS. SINCE	EXTENT OF DAMAGE	REPORTS FORM	REPORTS SERIAL NO.	REPORTS DATE
Hurricane P.3872					Fuselage damaged just in front of fin - empennage badly damaged			
ENGINE								

REFERENCE TO REPORTS

UNIT OR COMMAND	FILE NO	DATE
Overseas H.Q.	21-2	28-8-40

P 2P PP FI WO AG AO OC Pass

TELEGRAPHIC REPORTS:
SIGNAL NO: DATE:
UNIT OR COMMAND: DATE:

DUTY ON WHICH ENGAGED:

NATURE OF ACCIDENT & STAGE OF FLIGHT:

P.3872 was sitting on drome with damaged tail wheel and was hit by taxying P.3869.

PRIMARY CAUSE:

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:

DATE: MULT

COMPOSITION: TCA/PCT MA/XA

RECOMMENDATIONS:

ACTION TAKEN:
(a) Disciplinary (b) Technical (c) other

Recorded by Date

Checked by Date