CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 8927

Title: de Havilland Moth, Tiger I serial:8927 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-April-19. Tiger Moth s/n 8927. This accident involved 1 person. Dickinson JR

Keywords: RCAFTiger Moth ,8927,4 EFTS,4 Elementary Flying Training School,St Robert Quebec,1943-April-19,DickinsonRCAF L20

Created: 1943-04-19

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#8927

PILOT | OTHERS | AIRFRAME FAILURE | ENGINE FAILURE

CAUSES OF ACCIDENTS

| | | |

DUTY ON WHICH ENGAGED:
Practice sequences 6A,B,C, 10, 15.

COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
D-14.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:
Pilot was making spins. While over fairly high hill he got caught in the up and down currents, and by time he got away he had lost his bearing and made precautionary landing 15 mi. north in snow-covered field.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:
51. Lost.

ACTION TAKEN:
(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY DATE

CHECKED BY DATE

R.C.A.F. FORM L20 REQ. 1247 10M—15-11-41