CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 4029/359

Title: Tiger Moth serial:4029/359 - Crash Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-July-07. Tiger Moth s/n 4029/359. This accident involved 1 person. Stevenson

Keywords: RCAFTiger Moth ,4029/359,2 EFTS,2 Elementary Flying Training School,Aerodrome,1943-July-07,StevensonRCAF L20

Created: 1943-07-07

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
2 E.F.T.S. Ft. William, Ont.	2	6 miles N.W. Main aerodrome	7-7-43	1430

H.Q. FILE

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
Tiger Moth	4029/359	Nil	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Stevenson	LAC	R171883	PP	Nil

F.L.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
	4

32

ENGINE	ENGINE NUMBER (S)
G.Major	7025/81525 Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL
3	3	25	26	25	26

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY

INJURY: FATAL, INJ., 3RD, S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Solo Seq. 14-16-17-22-25

NATURE OF ACCIDENT:

Recovered from spin, flew straight and level for approx. a minute. On increasing R.P.M. for climbing the engine suddenly quit. Force landed without damage to A/C

CLASSIFICATION:

54. Engine failure in the air (Obscure)

SECONDARY OR CONTRIBUTORY FACTORS:

TECHNICAL OFFICER'S REPORT:

No mechanical defect found.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43