CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 11225

Title: Avro Anson Mk. II serial:11225 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-September-03. Anson II s/n 11225. This accident involved 5 people. Barber A, Beasley RG, Jacques A, Kirby HJ, Middleton GS

Keywords: RCAFAnson II,11225,1 NAGS,1 Naval Air Gunnery School,Aerodrome,1943-September-03,Barber,Beasley,Jacques,Kirby,MiddletonRCAF L20

Created: 1943-09-03

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#11225

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
1 N.A.G.S. Yarmouth	E	M.A.	3-9-43	0845

H.Q. FILE 1100-112-25

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON II	11225	"B"		X	X	

PERSONNEL		RANK	NUMBER	DUTY	INJURIES
Kirby, H.J.	FX		98510	OC	Uninj.
Barber, A.	FX	ALA	96751	OC	Uninj.
Beasley, R.G.	FX	ALA	86982	OC	Uninj.
Jacques, A.		A/MA	93572	OC	Uninj.
Middleton, G.S.		AM(E)	92691	OC	Uninj.

NAIF-A

SIGNAL

NO.	DATE
T.537	3-9

D 14 (REVISED)

NO.	CHECKED
1	X

#5

ENGINE	ENGINE NUMBER (S)	
Jacobs L6MB	14585/11576	Nil
	14584/11575	Nil

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STATIRY
INJURY
FATAL
INJ.
3RD
S

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

NATURE OF ACCIDENT:

While starting a/c engines caught fire.

TECHNICAL OFFICER'S REPORT:

Suspected electrical fault in wiring aft of relay panel on stbd side.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

~~33. Technical defect.~~

11. Others 11

SECONDARY OR CONTRIBUTORY FACTORS:

30. Fire - On ground

30

ACTION TAKEN:

Nil

R. C. A. F. L 20 (REVISED)
7M-4-43 (3202) K. P. 5051
H. Q. 885-L 20

C. C. LTD. 7084-43