ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
2 W.S.,F.S. Shepard, Alta.	4	Beiseker, Alta.	27-11-43	1400

H.Q. FILE 1100-3651

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
FLEET FORT II	3651	NIL	x		x	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
Jeal C.R.	SGT	R131940	P	Uninj.
Eaton J.D.	LAC	R199857	WO	Uninj.

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
#10	✓

#14

ENGINE	ENGINE NUMBER (S)
Jacobs L6MB	19791/25903 NIL

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE SOLO	ON TYPE DUAL	TOTAL SOLO	TOTAL DUAL
40	22	600	1	699	101

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING

TAXYING

LANDING

TAKE-OFF

FLIGHT

STAT'RY

FATAL

INJURY

INJ.

3RD

S

RAF

M

N

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

W/T Exercise.

NATURE OF ACCIDENT:

Engine smoking and missing. Dropped rev's badly. Precautionary landing made half mile S.E. Town of Beiseker.

TECHNICAL OFFICER'S REPORT:

No. 7 piston has started to break up, ro, pin, pieces of piston and piston rings into the crankcase. An engine change is required

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS:

SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

58. Precautionary landings.

ACTION TAKEN:

NIL.