CASPIR.warplane.com

CASPIR Aircraft Accident Cards

Serial: 6883

Title: Avro Anson Mk. I serial:6883 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1943-December-29. Anson I s/n 6883. This accident involved 1 person. Nil

Keywords: RCAFAnson I,6883,7 AOS,7 Air Observer School,Aerodrome,1943-December-29,NilRCAF L20

Created: 1943-12-29

Link: https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6883

ACCIDENT CLASSIFICATION

UNIT	COM.	PLACE	DATE	TIME
7 A.O.S.	2	Aerodrome	29-12-43	1330

H.Q. FILE 1100-68-83

A/C TYPE	NO.	CRASH CAT.	S.E.	M.E.	DAY	NIGHT
ANSON I	6883	"E"		X	X	

PERSONNEL	RANK	NUMBER	DUTY	INJURIES
NIL				

SIGNAL

NO.	DATE

D 14 (REVISED)

NO.	CHECKED
#6	

#24

NAFP

ENGINE	ENGINE NUMBER (S)
Cheetah IX	P. 28704 2/AS37134 NIL
	S. 10682/AS31012 NIL

HOURS FLOWN BY PILOTS

INST.	NIGHT	ON TYPE		TOTAL	
		SOLO	DUAL	SOLO	DUAL

TYPE OF A/C

TYPE OF UNIT

CATEGORY

COMMAND

MONTH

STAGE OF FLIGHT

FORCED LANDING
TAXYING
LANDING
TAKE-OFF
FLIGHT
STAT'RY
INJURY: FATAL, INJ., 3RD, S, RAF, M, Z

ACCIDENT CLASSIFICATION

PURPOSE OF FLIGHT:

Navigation exercise

NATURE OF ACCIDENT:

Both engines operated normally until rocker standard broken on Port motor

TECHNICAL OFFICER'S REPORT:

Broken exhaust valve standard on #5 cylinder Port Motor.

COURT OF INQUIRY OR INVESTIGATING OFFICER'S REPORT:

FINDINGS: SUMMARY No.

CLASSIFICATION:

54. Engine failure in the air.

SECONDARY OR CONTRIBUTORY FACTORS:

NIL.

ACTION TAKEN:

NIL.

R.C.A.F. L 20 (REVISED)
7M-4-43 (3202) K.P. 5051
H.Q. 885-L 20

C. C. LTD. 7084-43