

## CASPIR Aircraft Accident Cards

---

**Serial:** 2689

**Title:** North American Harvard Mk.II serial:2689 Accident Card

**Author:** Royal Canadian Air Force (RCAF)

**Subject:** This accident involved 1 aircraft on 1941-August-15. Harvard s/n 2689. This accident involved 1 person. Long HW This accident had 1 fatality. Leading Aircraftman Harry William Long RAAF Killed in Flying Accident service no:403352 Harvard 2689

**Keywords:** RCAFHarvard ,2689,2 SFTS,2 Service Flying Training School,Uplands,1941-August-15,LongRCAF L20

**Created:** 1941-08-15

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#2689>



DUTY ON WHICH ENGAGED:

Night Flying Training

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft crash following take off

CIRCUITS & LANDINGS AT NIGHT. AIRCRAFT  
CRASHED IN FIELD 3 MILES WEST OF AERODROME  
APPROXIMATELY 10 MINUTES AFTER TAKING-OFF.

PRIMARY CAUSE:

Obscure.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

COURT OF INQUIRY

DATE: 15-8-41

COMPOSITION:

PRESIDENT - S/L ARCHAMBAULT, L.G.G.J.

MEMBER - F/L DAVID, L. N.

MEMBER - BYERS, A.G.

RECOMMENDATIONS:

MORE COCKPIT DRILL SHOULD BE INSISTED UPON.

ATTENTION SHOULD BE PAID TO THE OVER-TIREDNESS OF THE  
PUPILS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_