

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE			
CAUSES OF ACCIDENTS											
UNIT 4 S.F.T.S. Saskatoon, Sask. No.2		COM.		PLACE Aerodrome				DATE 4-8-41		TIME 0800	
A/C TYPE Crane		No. 7839		CRASH CAT. C 6		SE		ME X		DAY X NIGHT	
NAME		RANK		No.		DUTY		INJURIES		SERIOUS	
Cameron, L.H.		P/O		J3734		FI		Uninjured		FATAL INJURY	
Connor, R.H.		RAF		LAC		PP		Uninjured			
										CARD SERIAL No.	
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE	
Crane		7839		Slight						HOURS FLOWN BY PILOTS	
Jacobs		4218		Slight						INST. NIGHT	
Jacobs		4219								ON TYPE	
										TOTAL	
										LAST 6 MOS	
SIGNAL No & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE	
D195 4-8-41											
NATURE OF ACCIDENT											

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

DATE :

COMPOSITION:

RECOMMENDATIONS:

Inability of pupil pilot to
stop swinging of aircraft

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Error on part of instructor in
not taking over sooner

RECORDED BY

DATE _____

CHECKED BY

DATE _____