

DUTY ON WHICH ENGAGED:

SOLO FLYING TRAINING PRACTICE.

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

TWO AIRCRAFT ATTEMPTING TO LAND INTO SUN
WHEN HIGHER LANDED ON TOP OF LOWER.

DATE:

COMPOSITION:

LCR/MCA/10VS

RECOMMENDATIONS:

LCR/XA

PRIMARY CAUSE:

INEXPERIENCE ON THE PART OF THE PILOT IN THAT
HE FAILED TO OBSERVE OTHER AIRCRAFT WHEN LANDING
INTO SUN.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Warning all pilots to take
special care under these
conditions.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft colliding with another
aircraft in the air.

RECORDED BY

DATE

CHECKED BY

DATE