

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT										AIRFRAME FAILURE										ENGINE FAILURE											
OTHERS										CAUSES OF ACCIDENTS																					
UNIT Conversion Tr. Sqdn. Picton, Ont.										COM. I		PLACE Aerodrome, Picton				DATE 27-8-41		TIME 16:20													
A/C TYPE Yale										No. 3359		CRASH CAT. C.		SE X ME		DAY X NIGHT															
NAME										RANK		NO.		DUTY		INJURIES				SERIOUS											
Carr, H.D.										SGT		R62310		P.		Uninjured				FATAL		INJURY									
Reinhart, H.W.										P/O		C 6245				Uninjured															
																				CARD SERIAL No.											
TYPE A/F & ENGINE										No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS											
Yale										3359		Slight								INST NIGHT		ON TYPE		TOTAL		LAST 6 MOS					
Whirlwind																				DUAL SOLO		DUAL SOLO									
SIGNAL No & DATE										UNIT No & DATE		COM. No & DATE		REPORT		FILE		DATE													
A 127 27-8-41																															
NATURE OF ACCIDENT																															

CAUSES
 MISCELLANEOUS
 STAGE OF FLIGHT

PRIMARY
 HAND-O.
 INSTS.
 WEATHER
 DRINKS.
 ALG SURF.
 OTHER
 UND TD
 PRIMARY
 TAXIING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJURY
 3rd
 5

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Dual instructions circuits & Landings

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Ground looped on landing in cross-wind.

COMPOSITION:

LC/SC/CO/OW

RECOMMENDATIONS:

PRIMARY CAUSE:

Failure of left oleo leg resulted in buckling of left wing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE