

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
Practicing Sequence 25	OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	R 170
Aircraft ground looped and port w	
hit ground damaging oleo leg and	
port wing.	
	RECOMMENDATIONS:
PRIMARY CAUSE:	
Failure to correct initial swing	
after landing.	
	ACTION TAKEN:
	(A) Disciplinary (B) Technical (C) Other
	Instructor's Log Book endorsed "Landing - Error
	in Judgment"
	Aicraft to use grass landing strip when weather
	permits
SECONDARY CAUSE OF CONTRIBUTING PACTORS	• • • • • •
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
SECONDARY CAUSE OR CONTRIBUTING FACTORS: Ground loop	<del>-</del>
	RECORDED BY DATE
	<del>-</del>