

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Wing test.

Monthly Accident Return. ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot of aircraft 3173 taxied into rear of aircraft 2698 which was parked on taxi strip prior to take-off.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Pilot of aircraft 3173 failed to see aircraft 2698 preparatory to take-off.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Carelessness."
Pilot admonished.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft 3173 taxied into a/c 2698 - airscrew striking tail assembly and rear fuselage.

RECORDED BY

DATE

CHECKED BY

DATE