

))	DUTY ON WHICH ENGAGED: Night flying take offs and landings. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: INVESTIGATING OFFICER'S REPORT DATE: 24th September, 1941.
)	Aircraft went into spiral dive at approx. 600'. Pilot made partial recovery before striking ground.	G.E. Creighton, Squadron Leader RECOMMENDATIONS:
)))	Aircraft went into spiral dive at approx. 600'. Pilot unable to recover by instruments, making only partial recovery.	Strict compliance by all pilots with No. 14 S.F.T.S. Aylmer, Night Flying Instructions.
)	SECONDARY CAUSE OF CONTRIBUTION FOR	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER Nil
)	Aircraft struck the ground.	RECORDED BY DATE
)		CHECKED BY DATE