

32	JU.	31	TECH.	30	DISOB.	29	NEG'VE	28	INEXP'CE	27	MISCEL.	26	INSTRUCT.	25	FLT. CONTR.	24	OTHERS	23	PRIMARY	22	FL. CONTR.	21	MOV. SURFS.	20	STAB. SURFS.	19	W. STRUTS	18	LAND. GEAR	17	FLOATS	16	FUSE. OR HULL	15	TAIL SKID OR W.	14	ENGINE MOUNT.	13	MISCEL.	12	UND/TD	11	PRIMARY	10	FUEL SYS.	9	COOL. SYS.	8	IGNIT. SYS.	7	LUB'N SYS.	6	ENG. STR.	5	AIRSCREW A.	4	ENG. CONTR.	3	MISCEL.	2	UND/TD	1	PRIMARY	19	HAND Q.	18	INSTS.	17	WEATHER	16	DRKNS.	15	ALG SURF.	14	OTHER	13	UND/TD	12	PRIMARY	11	TAKING	10	LANDING	9	TAKE-OFF	8	FLIGHT	7	STATRY	6	FATAL	5	INJ.	4	INJ.	3	INJ.	2	INJ.	1	INJ.	32	RAF	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																																																																																																																								
CAUSES OF ACCIDENTS																																																																																																																																						
UNIT # 6 B. & G. S. COM. Mountain View, Ont. 1										PLACE Picton Aerodrome										DATE 10-9-41		TIME 15:30																																																																																																																
A/C TYPE Battle										No. 2023		CRASH CAT. B		SE x	ME	DAY NIGHT x																																																																																																																						
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																																																																																																																								
Keim, F.T.				P/O		C5895		P.		Uninjured				FATAL	INJURY																																																																																																																							
Sopuck, G.				LAC		R58995		OC	x	Uninjured																																																																																																																												
McCauley, J.E.				AC1		R80662		OC		Uninjured				CARD SERIAL No.																																																																																																																								
TYPE OF ENGINE										STAGE OF FLIGHT																																																																																																																												
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM	SERIAL No.	DATE		HOURS FLOWN BY PILOTS																																																																																																																												
Battle		2023		Serious						INST.	NIGHT	ON TYPE		TOTAL		LAST 6 MOS.																																																																																																																						
MERLIN		8412		SLIGHT						10	NIL			27:50		27																																																																																																																						
SIGNAL No & DATE				UNIT No. & DATE				COM. No & DATE				REPORT		FILE		DATE																																																																																																																						
NATURE OF ACCIDENT																																																																																																																																						

DUTY ON WHICH ENGAGED:

Familiarization flight.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**A/C taxied into frame building
after carrying out precautionary
landing due to weather.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Investigating Officer's Report

DATE: September 17th, 1941.

COMPOSITION:

Rogers, J.E.

Flight Lieutenant.

RECOMMENDATIONS:

NIL

TCC/PCT

PRIMARY CAUSE:

Pilot inexperienced.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

TAXIED INTO A BUILDING

RECORDED BY

DATE

CHECKED BY

DATE