

## CASPIR Aircraft Accident Cards

---

**Serial:** AS162

**Title:** Airspeed Oxford Mk. II serial:AS162 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1941-September-07. Oxford s/n AS162. This accident involved 1 person. Weller R

**Keywords:** RAFOxford ,AS162,34 SFTS,34 Service Flying Training School,Aerodrome,1941-September-07,WellerRCAF L20

**Created:** 1941-09-07

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS162>



DUTY ON WHICH ENGAGED:

Solo Pupil Training.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Monthly Accident Return.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil sol attempted to land with the u/c retracted against red light. Touched airscrews on ground and took off again & landed successfully with damaged airscrew.

DATE:

COMPOSITION:

oco/R/KSJ

RECOMMENDATIONS:

PRIMARY CAUSE:

Pupil attempting to land with u/c retracted.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action against pupil, and against aerodrome control for not firing red signal.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil not carrying out drill of vital action before landing.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_