

CASPIR Aircraft Accident Cards

Serial: AR919

Title: Airspeed Oxford Mk. I serial:AR919 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-September-13. Oxford s/n AR919. This accident involved 2 people. Elliott R, Sharpe SA

Keywords: RAFOxford ,AR919,34 SFTS,34 Service Flying Training School,Aerodrome,1941-September-13,Elliott,SharpeRCAF L20

Created: 1941-09-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AR919>

DUTY ON WHICH ENGAGED:

Night flying instruction.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Collapse of both undercarriage on heavy landing. Instructor ordered pupil to throttle back, and as pupil did so, aircraft began to fall. FI took over control, and opened throttles fully, but a/c hit the ground at the edge of the runway.

PRIMARY CAUSE:

Aircraft caught in down current over falling ground to east of runway.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

48 - Hour Report.

DATE:

COMPOSITION:

L H / J SAH / C SAH / W W O

RECOMMENDATIONS:

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

All pilots warned of the possibility of down current when landing over this fall of ground.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____