

DUTY ON WHICH ENGAGED:

WIRELESS TRAINING

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Investigating Officer's Report

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: 25TH, SEPTEMBER, 1941.

AIRCRAFT MADE FORCED LANDING AND WENT THROUGH WIRE FENCE--~~EXXKE~~

COMPOSITION:

F/O

Cardoza, S.J.

RECOMMENDATIONS:

Strict adherence to Maintenance Regulations.

PRIMARY CAUSE:

ENGINE THROTTLE CONTROL DISCONNECTED AS IT HAD NOT BEEN PROPERLY SECURED.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

DISCIPLINARY ACTION TAKEN AGAINST MAINTENANCE PERSONNEL

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

FORCED LANDED THROUGH WIRE FENCE

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____