

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																	
CAUSES OF ACCIDENTS																															
UNIT 6 S.F.T.S. Dunnville, Ont.								COM. 1				PLACE Near Kohler Field								DATE 8-10-41				TIME 11:30							
A/C TYPE Harvard								No. 2778				CRASH CAT. C 7				SE x		ME		DAY x		NIGHT									
NAME								RANK		NZ No.		DUTY		INJURIES				SERIOUS													
McPherson, A.M.								LAC		411917		P.		Uninjured				FATAL		INJURY											
																CARD SERIAL No.															
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLN BY PILOTS																			
Harvard		2778		Serious								INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.											
Wasp S3HL Y141 5808												15		1		16 4		58 44													
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE											
A 499 9-10-41																															
NATURE OF ACCIDENT																															

HANDLING
 INSTS.
 WEATHER
 DRINKS.
 ALG SURF.
 OTHER
 UND'TD
 PRIMARY
 TAXING
 LANDING
 TAKE-OFF
 FLIGHT
 STATRY
 FATAL
 INJ.
 3RD.
 5th

MISCELLANEOUS

STAGE OF

DUTY ON WHICH ENGAGED:

Cross country flight.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landing.

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

**Carelessness - error in judgment
Inexperience.**

Nil

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed "Carelessness"

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

**Carelessness for not staying closer
to Kohler while landing - Undershot.**

RECORDED BY

DATE

CHECKED BY

DATE