

UTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER
instrument flying training.	OR COMMANDING OFFICER'S REPORT: R 170
ATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: (5/255)
round loop . AIRCRAFT SWUNG TO RIGHT ON	COMPOSITION.
ANDING, PILOT FAILED TO CHECK SWING, RESULT N A GROUND LOOP.	I NG
	RECOMMENDATIONS:
	Nil
RIMARY CAUSE:	
Pilot failed to check swing.	
ERROR IN JUDGMENT ON THE PART OF THE PILOT	
IN THAT HE FAILED TO CHECK SWING.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	All possible action being taken to eliminate ground loops.
ECONDARY CAUSE OR CONTRIBUTING FACTORS:	
MRGRAFT SHOUND LOOPED.	
San tare F San Cond Loope Loop	RECORDED BY DATE
	CHECKED BY DATE