

	,)
É)	DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER)
	`	OR COMMANDING OFFICER'S REPORT:	,
	,	R 170)
ŀ)	NATURE OF ACCIDENT AND STAGE OF FLIGHT: DATE:)
		A/C swung to left on landing. Pilot COMPOSITION:)
		applied right rudder to correct swing	,
		to the left. The application of right	
		rudder was so violent that A/C swung)
		to the right. Pilot failed to RECOMMENDATIONS: control swing to the right and A/C)
		ground looped to the right.	
	`	PRIMARY CAUSE: Nil	
	,	Pilot over corrected on swing to left	
		causing A/C to ground loop to the)
)	right.)
ĺ)	ACTION TAKEN:	`}-
	`	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
	,)
)	Log Book endorsed "Carelessness")
))
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS:	j
	`	Oleo Legs buckled in ground loop	
	,	and port wing and airscrew struck RECORDED BY DATE)
)	the ground.	
)#	CHECKED BY DATE)
);)
Si.	2.20		_