

DUTY ON WHICH ENGAGED:

Practising circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

On landing bolts sheared off radius rod, driving it through port tire.

DATE:

COMPOSITION:

L M / CDM

RECOMMENDATIONS:

PRIMARY CAUSE:

Structural failure.

Nil

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

More frequent renewal of bolts.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Bolts sheared off on radius rod, driving rod thru port tire.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____