

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Solo Flying Training.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

After landing pilot failed to zigzag aircraft while taxiing and struck fire extinguisher on starting battery box.

1 CO/PST

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Negligence of student in taxiing by failing to take precautionary measure.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

1 days detention

7 days C.E.

(A.F.A. 39 1 (b)).

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircrew struck handle of starting battery box.

RECORDED BY

DATE

CHECKED BY

DATE