

CASPIR Aircraft Accident Cards

Serial: AS207

Title: Airspeed Oxford Mk. II serial:AS207 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-October-04. Oxford s/n AS207. This accident involved 4 people. Driver JW, Stitt CH, Sutherland H, Watson A

Keywords: RAFOxford ,AS207,35 SFTS,35 Service Flying Training School,Reserve Aerodrome,1941-October-04,Driver,Stitt,Sutherland,WatsonRCAF L20

Created: 1941-10-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS207>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

DUAL INSTRUCTION

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

CFM/123

AIRCRAFT LANDED WITH UNDERCARRIAGE

COMPOSITION:

RETRACTED

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Airscrew came in contact with ground
after take-off.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Error of judgment on part of pilot.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____