

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Flying training.

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Oxford AS172 stationary was taxied
into by Oxford AS784

RECOMMENDATIONS:

PRIMARY CAUSE:

Nil

Lights failed on Oxford AS172

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further check on condition of batteries prior to
night flying.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Lights failed on AS172

RECORDED BY

DATE

CHECKED BY

DATE