

## CASPIR Aircraft Accident Cards

---

**Serial:** AR850

**Title:** Airspeed Oxford Mk. I serial:AR850 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1941-October-11. Oxford s/n AR850. This accident involved 1 person. Roberts EST

**Keywords:** RAFOxford ,AR850,34 SFTS,34 Service Flying Training School,Medicine Hat Aerodrome,1941-October-11,RobertsRCAF L20

**Created:** 1941-10-11

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AR850>



DUTY ON WHICH ENGAGED:

Night flying Solo

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R 170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Aircraft landed with undercarriage retracted.

RECOMMENDATIONS:

PRIMARY CAUSE:

Pupil failed to lower undercarriage.

Nil

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action and endorsement of Log Book.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Failed to carry out Drill of Vital Actions.

RECORDED BY

DATE

CHECKED BY

DATE