

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
Circuits and landings. NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: COMPOSITION:  M
Aircraft swung after landing. Harsh application of brake and rudder caused aircraft to tip up on nose.	COMPOSITION:
	RECOMMENDATIONS:
PRIMARY CAUSE:	Nil
Inexperience on part of pilot in using excessive brake to correct	
swing.	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
	Log book endorsed "Inexperience in Use of Brakes."
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft tipped up on mose.	RECORDED BY DATE