

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Aircraft taxiing to parking area

OR COMMANDING OFFICER'S REPORT:

after landing

R17C

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pilot was watching port side and turned to starboard into parked aircraft 2942 belonging to 13 S.F.T.S.

COMPOSITION:

MULTI
7CA/PCT
MH/AG

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Carelessness on part of pilot in that he taxied his aircraft into another.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

LAC Woods awarded 120 hours detention.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Starboard wing of 2870 crashed into port wing of 2942 doing damage to both wings.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____