

PILOT		OTHERS		AIRFRAME FAILURE				ENGINE FAILURE					
CAUSES OF ACCIDENTS													
UNIT 1 S.F.T.S.		COM. 1		PLACE Relief Ground, Edenvalle				DATE 19-11-41		TIME 15:00			
Camp Borden, Ont.		1		Relief Ground, Edenvalle				H.O. FILE 100-31-60					
A/C TYPE Yale Harvard D		No. 3119 3139D		CRASH CAT. C 1 1/2 C 1 1/2		SEX X		ME		DAY NIGHT X			
NAME			RANK	No.	DUTY	INJURIES			SERIOUS				
Williams, R.G. 3169			LAC	401686	F.	Uninjured.			FATAL	INJURY			
MARRINER, G.E. 3449			LAC	R102520	P	UNINJURED							
									CARD SERIAL No.				
TYPE A/F & ENGINE	No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS							
Harvard 3169	3169	Slight				INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS	
YALE 3119	3119	SLIGHT				12	1		DUAL	SOLO	DUAL	SOLO	
Wasp S3H1 4741	4741	NIL				22	2						
WRIGHT WHIRL. 15050	15050	NIL											
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE			
C 124		20-11-41											
NATURE OF ACCIDENT													

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS

STAGE OF FLIGHT

- UNDTD
- PRIMARY
- HAND O.
- INSTS.
- WEATHER
- DRANS.
- AL G SURF.
- OTHER
- UNDTD
- PRIMARY
- TAXING
- LANDING
- TAKE-OFF
- FLIGHT
- STAIRY
- FATAL
- INJ.
- 3RD.
- 2
- 1

32)
31)
30)
29)
28)
27)
26)
25)
24)
23)
22)
21)
20)
19)
18)
17)
16)
15)
14)
13)
12)
11)
10)
9)
8)
7)
6)
5)
4)
3)
2)
1)

JU.)
TECH.)
DISOB.)
INEXP NCE)
MISCEL.)
INSTRUCT.)
FLT CONTR.)
OTHERS)
PRIMARY)
FL CONTS.)
MOV. SURFS.)
STAB. SURFS.)
W. STRUTS)
LAND GEAR)
FLOATS)
FUSE. OR HULL)
TAIL SKID OR W)
ENGINE MOUNT.)
MISCEL.)
UNDTD)
PRIMARY)
FUEL SYS.)
COOL SYS.)
IGNIT. SYS.)
LUB N SYS.)
ENG. STR.)
AIRSCREW A.)
ENG CONTS.)
MISCEL.)
UNDTD)
PRIMARY)
HAND O.)
INSTS.)
WEATHER)
DRANS.)
AL G SURF.)
OTHER)
UNDTD)
PRIMARY)
TAXING)
LANDING)
TAKE-OFF)
FLIGHT)
STAIRY)
FATAL)
INJ.)
3RD.)
2)
1)

1)
2)
3)
4)
5)
6)
7)
8)
9)
10)
11)
12)
13)
14)
15)
16)
17)
18)
19)
20)
21)
22)
23)
24)
25)
26)
27)
28)
29)
30)
31)
32)

DUTY ON WHICH ENGAGED:

Spins - Aerobatics

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

M. J. I. ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Yale 3169 was on taxi strip waiting to take off - Harvard 3169 taxied into it.

DATE:

7/24/57

COMPOSITION:

TCR/XA

RECOMMENDATIONS:

NIL

PRIMARY CAUSE:

Carelessness on part of pilot of Harvard 3169

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

DISCIPLINARY ACTION TAKEN AGAINST PILOT.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT TAXIED INTO YALE 3449.

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____