

			\cdot
DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER		
Night solo circuits and	OR COMMANDING OFFICER'S REPORT:		
landings.	R170		
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	The second second	7
On landing pilot applied brakes	COMPOSITION: LM/H/-	1/0 M/X6.	
frozen runway caused aeroplane to	<i>'</i>	•	
skid When it struck soft mud at			
the end of runway aircraft nosed	DECOMMENDATIONS		
over on its back resulting in	RECOMMENDATIONS:		•
serious damage to engine and airfra	ame.		
PRIMARY CAUSE:	NIL		
Frozen runways with soft mud at			
end of runway, caused AIRCRAFT TO NOSE	e see		, •
OVER ON ITS BACK WHEN STRIKING THE SOFT			
MUD.	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTI	HER	
	RUNWAYS BEING CLEANED.		
	TOTAL CEPTIEPS		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:			
Aircraft struck soft mud and nosed over on its back.			
		RECORDED BY	DATE
FROZEN: RUNWAYS, WITH SOFT MUD AT END OF RUNWAY.			
BRAKES INEFFECTIVE ON ICY RUNMAY.		CHECKED BY	DATE
))))