

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ802

**Title:** North American Harvard Mk. II serial:AJ802 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1941-November-29. Harvard s/n AJ802. This accident involved 1 person. Blackshaw H

**Keywords:** RAFHarvard ,AJ802,34 SFTS,34 Service Flying Training School,Aerodrome,1941-November-29,BlackshawRCAF L20

**Created:** 1941-11-29

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ802>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Running up engine.

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Chock slipped while airman was running up engine and in endeavouring to control the aircraft it was tipped up until the airscrew tip came in contact with the ground.

RECOMMENDATIONS:

PRIMARY CAUSE:

Nil

*N.A.F.A.*

Chock slipped while aircraft being run up.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken with airman. Local purchase of suitable chocks being made.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Insufficient supply of suitable chocks.

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_